



校对								
审核								
工艺								

Legenda esploso 35603 / LDWP520

Parte nr.	Codice	Descrizione (ITA)	Description (ENG)	EAN
NA	96102	bobina Hyundai motopompa 4T	coil	8028815961028
12	96204	campana innesto tubo mandata motopompa 2T	pipe connection case	8028815962049
NA	96306	carburettore Hyundai motopompa 2T	carburetor	8028815963060
from 1 to 5 included	96426	premistoppa motompompa 2T	stuffing box	8028815964265
NA	96904	gruppo avviamento Hyundai motopompa 2T	recoll starter assembly	8028815969048
NA	35224	carburettore - per decespugliatore motop. 2T	carburetor	8028815352246